

**QUARTERLY DETENTIONS IN THE BLACK SEA REGION**

**FIRST QUARTER 2005**

<b>IMO #</b>	<b>Ship name</b>	<b>Flag</b>	<b>Year of build</b>	<b>GT</b>	<b>Ship type</b>	<b>Ship class</b>	<b>Owner</b>	<b>Reporting Authority</b>	<b>Port of detention</b>	<b>Date of det.</b>	<b>Date of release</b>	<b>Nature of def. (Responsible RO, if any)</b>
7382809	NINA S	Georgia	1974	3389	general cargo/multi-purpose ship	ISTHMUS MARITIME CLASSIFICATION	SEAGATE TRANSPORT INC. - UNITED KINGDOM	Romania	Constanta	03.01.2005	20.01.2005	ISM RELATED DEFICIENCIES, company responsibility and authority, different company name and address on doc/smc and c.s.r. ISM RELATED DEFICIENCIES, emergency preparedness, forms records not updated and training manual missing FIRE SAFETY MEASURES, fire prevention, cargo hold lighting in bad condition FIRE SAFETY MEASURES, readily availability of fire fighting equipment, emergency firepump couldn't be tested CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, certificates for master and officer, second engineer without appropriate coc MARPOL - ANNEX I, oil filtering equipment, bilge separator couldn't be tested
8110318	NASSAU PARADISE	Bahamas	1984	21193	bulk carrier	American Bureau of Shipping	TROJAN MARITIME INC. PIRAEUS	Romania	Constanta	03.01.2005	10.01.2005	SAFETY OF NAVIGATION, other (navigation), ship is not fitted with automatic identification system (a.i.s.)
6602032	LETF ALLAH	Syrian Arab Republic	1965	499	general cargo/multi-purpose ship	International Naval Surveys Bureau	HOURIEH ABDUL KADER ASSUM JENDI	Romania	Constanta	04.01.2005	06.01.2005	FIRE SAFETY MEASURES, fire pumps, emgcy fire pump not working properly

7432824	TERAISE M	Georgia	1974	1527	general cargo/multi-purpose ship	International Register of Shipping	ISM GROUP LTD, SYRIA	Romania	Constanta	04.01.2005	08.01.2005	SAFETY OF NAVIGATION, other (navigation), a.i.s. not fixed CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, certificates for master and officer, engine officer missing ISM RELATED DEFICIENCIES, safety and environmental policy, record and training manuals missing SOLAS RELATED OPERATIONAL DEFICIENCIES, abandon ship drills, performed unsatisfactory FIRE SAFETY MEASURES, readily availability of fire fighting equipment, co2 launching post not as per requirements and alarm system doesn't work properly
9039286	HISTRIA FAITH	Malta	1991	6036	general cargo/multi-purpose ship	Germanischer Lloyd	SEATIDE SHIPPING COMP.	Russia	Novorossiysk	05.01.2005	13.01.2005	FIRE SAFETY MEASURES, fixed fire extinguishing installation
6518308	ALEX	Georgia	1965	492	general cargo/multi-purpose ship	RMRS	Toliu Ltd. Georgia	Ukraine	Theodosia	05.01.2005	06.01.2005	0135 Minimum Safe Manning Document 0199 Other Ship's Certificates and documents
6728159	CAPTAIN SCHABAN	Saint Vincent and the Grenadines	1967	1202	general cargo/multi-purpose ship	International Naval Surveys Bureau	KERMAN TRANS. IZMIR, TURKEY	Romania	Constanta	07.01.2005	11.01.2005	ISM RELATED DEFICIENCIES, safety and environmental policy, records missing PROPULSION AND AUXILIARY MACHINERY, auxiliary engine, fwd generator out of order
7005683	ORION	Ukraine	1969	2478	general cargo/multi-purpose ship	Russian Maritime Register of Shipping	GUYS STD SHIPPING CONIKOLAE V-UKRAINE	Turkey	Kdz.eregli	10.01.2005	12.01.2005	SAFETY OF NAVIGATION, echo-sounding device, out of order FIRE SAFETY MEASURES, Ventilation, engine room funnel fire dampers inoperable FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, alarm inoperable
9171618	KOHO	Panama	1998	87417	bulk carrier	Nippon Kaiji Kyokai	TOYO SANGYO CO.,LTD.JAPAN	Turkey	Kdz.eregli	13.01.2005	14.01.2005	FIRE SAFETY MEASURES, Ventilation, and fire dampers of engine room funnel inoperable properly.by 2 ship crew can not operable stbrd fire and vent.damper. (Nippon Kaiji Kyokai)

5415119	AVRASYA	Korea, Democratic People's Republic	1962	2874	ro-ro passenger ship	Korea Classification Society (former Joson Classification Society)	Avrasya Shipping Co., Delaware, USA	Russia	Sochi	14.01.2005		LIFESAVING APPLIANCES, lifejackets, to be changed (Korea Classification Society (former Joson Classification Society) ) RADIOCOMMUNICATIONS, VHF radio installation, no dsc vhf transmission (Korea Classification Society (former Joson Classification Society) )
7123526	HAJEH HESEN	Syrian Arab Republic	1971	1597	general cargo/multi-purpose ship	Turkish Lloyd	Raouf Maritime Co. Tartous - Syria	Bulgaria	Varna	19.01.2005	21.01.2005	FIRE SAFETY MEASURES, Emergency Fire Pump, emergency fire pump room-dirty FIRE SAFETY MEASURES, Emergency Fire Pump, emergency fire pump - out of order LOAD LINES, ventilators, air pipes, casings, some ventilators air pipes-safety net - missing STABILITY, STRUCTURE AND RELATED EQUIPMENT, hydraulic and other closing devices/watertight doors, some fire dampers-not in operation ALARM SIGNALS, fire alarm, fixed fire system -co2 alarm out of order LIFESAVING APPLIANCES, lifeboat inventory, lifeboat's engine - oil tank-empty SAFETY OF NAVIGATION, charts, more of ship's charts not updated
6614841	KARTAL CK	Turkey	1966	1539	general cargo/multi-purpose ship	Turkish Lloyd	CK DENIZCILIK NAKLIYAT ve TICARET LTD.	Bulgaria	Bourgas	20.01.2005	21.01.2005	SHIP'S CERTIFICATES AND DOCUMENTS, minimum safe manning document, safety manning document on board-copy only (Turkish Lloyd) PROPULSION AND AUXILIARY MACHINERY, auxiliary engine, 1-2 out of order (Turkish Lloyd) PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, heavy leakages, a lot of rubbish and waste oil (Turkish Lloyd)
7332426	SERGEY GRITSEVETS	Ukraine	1973	3712	general cargo/multi-purpose ship	SHIPPING REGISTER OF UKRAINE (SRU )	UKRAINIAN DANUBE SHIPPING CO., ODESSA	Russia	Novorossiysk	24.01.2005	29.01.2005	FIRE SAFETY MEASURES, Ventilation, ventilation funnel of cargo holds flaps damaged FIRE SAFETY MEASURES, Ventilation, ventilation funnel of engine room corroded through STABILITY, STRUCTURE AND RELATED EQUIPMENT, other (stability/structure), superstructure heavy corroded

8898582	VILUYSK	Cambodia	1967	1652	general cargo/multi-purpose ship	International Register of Shipping	ORION SHIPPING & TRADING LTD.- ISTANBUL-TURKEY	Romania	Tulcea	25.01.2005	08.02.2005	SHIP'S CERTIFICATES AND DOCUMENTS, document of Compliance (DoC/ISM Code), annual verification is missing SHIP'S CERTIFICATES AND DOCUMENTS, prevention of pollution by oil (IOPP), supliment to iopp certificate form a not complete SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety equipment (including Exemption), ais fitted on board not recorded in the safety equipment certificate (International Register of Shipping) SAFETY OF NAVIGATION, charts, sulina approaches chart and sulina channel chart are missing STABILITY, STRUCTURE AND RELATED EQUIPMENT, steering gear, in steering gearroom telephone to emergency purposes is missing FIRE SAFETY MEASURES, Emergency Fire Pump, emergency fire pump not working properly LOAD LINES, doors, all doors from all decks are with old rubber gaskets STABILITY, STRUCTURE AND RELATED EQUIPMENT, decks - corrosion, all decks are deeply corroded STABILITY, STRUCTURE AND RELATED EQUIPMENT, bulkheads - cracking, bulkheads of the hatches are cracked and holed STABILITY, STRUCTURE AND RELATED EQUIPMENT, bulkheads - cracking, bulkheads between a LOAD LINES, covers (hatchway-, portable-, tarpaulins, etc LOAD LINES, covers (hatchway-, portable-, tarpaulins, etc MOORING ARRANGEMENTS (ILO 147), other (mooring)
8507298	VISPATAURINI	India	1988	11996	general cargo/multi-purpose ship	Bureau Veritas	POLARIS MARITIME MANAGEMEN T	Russia	Novorossiysk	25.01.2005		PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, engine room is very dirty LOAD LINES, doors, remote control of watertight door in engine room is not in working condition ALARM SIGNALS, fire alarm, panel isn` t working PROPULSION AND AUXILIARY MACHINERY, other (machinery), seal of deadwood in engine room have leakage of sea water, seal of deadwood to be surveyed by class and repaired
7627479	NEVY	Slovakia	1976	4043	general cargo/multi-purpose ship	Lloyd's Register of Shipping	HH BROTHERS MARITIME LIMITED ,VARNA, BULGARIA	Romania	Constanta	27.01.2005		LIFESAVING APPLIANCES, lifeboats, std.-side lifeboat engines couldn` t be started

6606090	LADY NOURA	Korea, Democratic People's Republic	1966	999	general cargo/multi-purpose ship	DBS	Ibrahim Mansour	Ukraine	Odessa	27.01.2005	01.02.2005	1565 Automatic Identification System (AIS)
8866943	ARAS 4	Georgia	1968	2457	general cargo/multi-purpose ship	Russian Maritime Register of Shipping	VENDA IMPEX L.L.C.	Romania	Constanta	28.01.2005	31.01.2005	SHIP'S CERTIFICATES AND DOCUMENTS, other (certificates), several ship's flag certificates are in copy RADIOCOMMUNICATIONS, MF radio installation, gmdss mf-dsc test couldn't be performed by ship's deck officers
5166134	GNOCCHI	Cambodia	1963	2812	general cargo/multi-purpose ship	International Register of Shipping	KMS ENTERPRISES-MARSHAL ISLANDS	Romania	Constanta	28.01.2005	28.01.2005	FIRE SAFETY MEASURES, fire pumps, emergency fire pump does not work properly RADIOCOMMUNICATIONS, MF radio installation, to g.m.d.s.s. instalation on dsc, m/f test couldn't be performed by ship's deck officers.
9074987	KRITI AMBER	Greece	1995	31330	combination carrier	Lloyd's Register of Shipping	AVIN INTERNATIONAL S.A. GREECE	Russia	Novorossiysk	30.01.2005	01.02.2005	MOORING ARRANGEMENTS (ILO 147), anchoring devices, port side anchor not drop during mooring operation (Lloyd's Register of Shipping)
6919514	REEF	Ukraine	1968	2406	general cargo/multi-purpose ship	UKRENIAN REGISTER OF SHIPPING (URS)	GOLDEN GATE LTD	Russia	Novorossiysk	01.02.2005	05.02.2005	MOORING ARRANGEMENTS (ILO 147), anchoring devices, anchor (st.side) missing
8842583	DNEPR-4	Ukraine	1990	3086	general cargo/multi-purpose ship	Russian Maritime Register of Shipping	JOINT STOCK SHIPPING COMPANY "UKRRICHFLOT" KIEV-UKRAINE	Turkey	Kdz.eregli	01.02.2005	02.02.2005	FIRE SAFETY MEASURES, Ventilation, all accomodation and eng.room vent.and fire dampers improperly closing and some of dampers cover missing. PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, engine room bilges with oily and cleanliness. LOAD LINES, ventilators, air pipes, casings, hold ventilations improperly closing and poor maintenance
8898582	VILUYSK	Cambodia	1967	1652	general cargo/multi-purpose ship	International Register of Shipping	ORION SHIPPING & TRADING LTD.-ISTANBUL-TURKEY	Romania	Tulcea	02.02.2005	08.02.2005	

6619712	OSOGOVO	Bulgaria	1966	5747	bulk carrier	FLAG STATE	NAVIGATIO N MARITIME BULGAREV ARNA- BULGARIA	Turkey	Kdz.eregli	02.02.2005	03.02.2005	RADIOCOMMUNICATIONS, reserve source of energy, navtex inoperative with reserve source of energy. SAFETY OF NAVIGATION, signalling lamp, aldis lamp inoperative PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, bilges and fuel seperators area.
8802337	CLIPPER	Malta	1987	6066	general cargo/multi-purpose ship	HRS	CLIPPER SHIPPING Ltd.	Ukraine	Mariupol	06.02.2005	09.02.2005	935
7322196	BLUE BABY	Malta	1973	4543	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	BLUE AND GREEN SHPPNG CO MALTA	Turkey	Samsun	10.02.2005		SAFETY OF NAVIGATION, magnetic compass, magnetic compass emergency light iz out of order (Nippon Kaiji Kyokai) FIRE SAFETY MEASURES, other (fire safety), there are open electr cables near cusne (Nippon Kaiji Kyokai) MARPOL - ANNEX I, oil filtering equipment, oilyl water seperator s out of order (Nippon Kaiji Kyokai) PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, blige water s full n engineer room (Nippon Kaiji Kyokai)
7521194	FAIAL	Mongolia	1977	2417	general cargo/multi-purpose ship	COLAMBIA AMERICAN REGISTRY ( CAR )	TIGER SHIPPING INC	Russia	Novorossiysk	11.02.2005	13.02.2005	SHIP'S CERTIFICATES AND DOCUMENTS, minimum safe manning document, date of expair SHIP'S CERTIFICATES AND DOCUMENTS, other (certificates), provisional certificate of registry LOAD LINES, ventilators, air pipes, casings, ventilation on forecastle isn` t watertight FIRE SAFETY MEASURES, Ventilation, ventilation device from engine room corrosion through LOAD LINES, cargo and other hatchways, seal covers , rubber partly broken
7946617	SALIH UNLU	Turkey	1975	659	general cargo/multi-purpose ship	Turkish Lloyd	EMSAN DENIZCILIK SANAYI TICARET AS, ISTANBUL-TURKEY	Russia	Novorossiysk	12.02.2005		STABILITY, STRUCTURE AND RELATED EQUIPMENT, hull - corrosion FIRE SAFETY MEASURES, Ventilation

6824202	PALLADA	Ukraine	1968	8326	ro-ro cargo ship	SHIPPING REGISTER OF UKRAINE	VIVAL MARITIME LTD ODESSA-UKRAINE	Turkey	Longuldak	14.02.2005	16.02.2005	FIRE SAFETY MEASURES, personal equipment, portable fire extinguishers several nozzle missing and poor condition. STABILITY, STRUCTURE AND RELATED EQUIPMENT, decks - corrosion, port and starboard sides trails existing crack and corrosion PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, and oily of of engine bilges. FIRE SAFETY MEASURES, fire pumps, emg. fire pump inoperative.
8942917	TOLSTOY	Korea, Democratic People's Republic	1971	3994	general cargo/multi-purpose ship	MARITIME BUREAU OF SHIPPING	JETSAR LIMITED, 35, BOULEVARD GAGILINA PERM 614060 RUSSIA	Turkey	Trabzon	14.02.2005		SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety equipment (including Exemption), sec form e not filled completely (Korea Classification Society (former Joson Classification Society) ) FIRE SAFETY MEASURES, fire fighting equipment and appliances, fire hydrant pipe holed on poop deck (Korea Classification Society (former Joson Classification Society) )

7946928	SPRING 1	Korea, Democratic People's Republic	1978	883	general cargo/multi-purpose ship	PHOENIX	BLUE LAND MARITIME INC.	Turkey	Kdz.eregli	15.02.2005		SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety equipment (including Exemption), expired. SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety construction (including Exemption), expired. SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety radio (including Exemption), expired. SHIP'S CERTIFICATES AND DOCUMENTS, safety management certificate (SMC/ISM Code), expired. SHIP'S CERTIFICATES AND DOCUMENTS, load lines, expired. SHIP'S CERTIFICATES AND DOCUMENTS, prevention of pollution by oil (IOPP), expired. CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, other (STCW), vessel manned with 11 persons, but vessel has and record to safety equip. for 10 person). RADIOCOMMUNICATIONS, reserve source of energy, missing for navtex. ALARM SIGNALS, other (alarms), co2 alarm unit inoperable. LIFESAVING APPLIANCES, launching arrangements for rescue boats, release hook inoperable properly PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, and bilges. ISM RELATED DEFICIENCIES, safety and environmental policy, sms manual not crew working language FIRE SAFETY MEASURES, jacketed piping system for hi
6823155	ALALAA II	Korea, Democratic People's Republic	1968	1229	general cargo/multi-purpose ship	MARITIME BUREAU OF SHIPPING	SHARM SHIPPING CO, DELAWARE-USA	Romania	Constanta	16.02.2005	24.02.2005	FIRE SAFETY MEASURES, fire fighting equipment and appliances, fire-fighting equipment inspection reports missing (fix co2, portable extinguishers, breathing apparatus, eebd-s)
8947620	LILYA KARASTOYAN OVA	Moldova	1964	1866	refrigerated cargo carrier	Russian Maritime Register of Shipping	POLISERVICE LTD.	Bulgaria	Bourgas	21.02.2005	23.02.2005	FIRE SAFETY MEASURES, Emergency Fire Pump, out of order (Russian Maritime Register of Shipping) LIFESAVING APPLIANCES, other (life-saving), emergency telephone of steering gear room to bridge-inoperative (Russian Maritime Register of Shipping)

5337862	A. ASLI	Cambodia	1959	2123	general cargo/multi-purpose ship	International Naval Surveys Bureau	METMAR METE DENIZCILIC - TURKEY	Romania	Constanta	21.02.2005	23.02.2005	SAFETY OF NAVIGATION, Automatic Identification System (AIS), on the bridge, automatic identification system (a.i.s.) missing LIFESAVING APPLIANCES, lifeboats, engine couldn't be started
7336575	JUPITER	Georgia	1974	1350	general cargo/multi-purpose ship	International Register of Shipping	UNITED MARINE CO.SRL, CONSTANT A-ROMANIA	Romania	Constanta	21.02.2005		FIRE SAFETY MEASURES, personal equipment, breathing apparatus are not ready for use FIRE SAFETY MEASURES, Emergency Fire Pump, couldn't be tested during inspection
8912493	FEHN BROKER	Antigua and Barbuda	1989	1524	general cargo/multi-purpose ship	Germanischer Lloyd	FEHN BEREEDER UNGS GMBH&CO. KG LEER GERMANY	Turkey	Kdz.eregli	21.02.2005		MARPOL - ANNEX I, oil filtering equipment, inoperative (Germanischer Lloyd) STABILITY, STRUCTURE AND RELATED EQUIPMENT, emergency lighting, batteries and switches, in engine room and accommodation missing. STABILITY, STRUCTURE AND RELATED EQUIPMENT, signs, indicators (WT doors, fire detectors, fire dampers, ventilation), imo sign for general fire fitting and safety equipment and emg. escapes missing. (Germanischer Lloyd)
7336745	SOTIRIA	Saint Vincent and the Grenadines	1973	1285	general cargo/multi-purpose ship	International Naval Surveys Bureau	DEKAMAR SHIPPING AND TRADING CO.LTD.- TURKEY	Romania	Constanta	22.02.2005	24.02.2005	LIFESAVING APPLIANCES, buoyant apparatus, in port side one man over board combined smoke and light is expired RADIOCOMMUNICATIONS, MF/HF radio installation, g.m.d.s.s. equipment ,mf-d.s.c. individual test cannot be performed by officers FIRE SAFETY MEASURES, Emergency Escape Breathing Device, all sets of emergency escape breathing devices are missing LIFESAVING APPLIANCES, lifeboat inventory, 3(three) red rockets parachutes, one magnetic compass and two buoyant rescue quitoes are missing
8317992	LASBEK	Liberia	1984	1597	chemical tanker	Germanischer Lloyd	COLUMBIA SHIPMANAGEMENT LTD, LIMASSOL-CYPRUS	Romania	Constanta	22.02.2005	23.02.2005	SAFETY OF NAVIGATION, lights, shapes, sound-signals, emergency navigation lights not working FIRE SAFETY MEASURES, Emergency Fire Pump, without sea water pressure FIRE SAFETY MEASURES, other (fire safety), fuel oil tanks quick closing devices couldn't be tested

8121331	NADALINA S	Georgia	1981	2368	general cargo/multi-purpose ship	International Register of Shipping	SEAGATE MARINE ROMANIA	Romania	Constanta	23.02.2005		SHIP'S CERTIFICATES AND DOCUMENTS, other (certificates), ship's statutory certificates are no longer valid (International Register of Shipping) ISM RELATED DEFICIENCIES, maintenance of the ship and equipment, ship under maintenance and repairs
7808918	TRITON	Panama	1978	4358	chemical tanker	Bureau Veritas	IONIA MANAGEMENT S.A. - PIRAEUS	Romania	Constanta	24.02.2005		SAFETY OF NAVIGATION, radar, one radar is out of order LIFESAVING APPLIANCES, lifeboats, stb.side lifeboat engine can not be started
7618430	CLAUDIA C	Korea, Democratic People's Republic	1978	1269	general cargo/multi-purpose ship	MBS	SOL MARITIME SERVICES S.R.L. CONSTANT A - ROMANIA	Romania	Constanta	28.02.2005		SHIP'S CERTIFICATES AND DOCUMENTS, other (certificates), the vessel is not fitted for psc inspection:ship's documents partly missing or not approved; solas requirements not fully implemented or missing; ism code not fully implemented; isps code not fully implemented; crew composition against safe manning certificate.inspection was suspended until vessel will be ready for inspection and on master/owner application form.
9065168	INDRA	Liberia	1994	21183	chemical tanker	Russian Maritime Register of Shipping	KUGU MENEDZMENTS SIA.- RIGA(LATVIA)	Romania	Constanta	28.02.2005		RADIOCOMMUNICATIONS, MF/HF radio installation, mf,dsc test performed- no reception
9063653	PIERRE DOUX	Bahamas	1994	9438	refrigerated cargo carrier	Bureau Veritas	Enterprises Shipping and Trading S.A. - Athens, Greece	Romania	Constanta	01.03.2005	04.03.2005	RADIOCOMMUNICATIONS, MF/HF radio installation, is not working.m/f test on dsc equipments can not performed
7229277	SEA TRADER	Bahamas	1972	1923	general cargo/multi-purpose ship	International Register of Shipping	WAW OVERSEA SHIPMANAGEMENT	Turkey	Samsun	02.03.2005		ADDITIONAL MEASURES TO ENHANCE MARITIME SAFETY, Continuous synopsis record, csr is missing (Lloyd's Register of Shipping)

7725350	ENRICHER	Panama	1981	13391	general cargo/multi-purpose ship	Bureau Veritas	Sea Lion Ship Management Pvt. Ltd.- 121 Shahid Bhagat Singh Rd.- Colaba - 400 005, Mumbai, India.	Romania	Constanta	04.03.2005	09.03.2005	LIFESAVING APPLIANCES, lifeboats, p-side life boat propeler shaft blocked FIRE SAFETY MEASURES, other (fire safety), d.g. high pressure pipe double jacket system partly disconnected
7024885	LEVON	Cambodia	1970	2478	general cargo/multi-purpose ship	International Register of Shipping	SOLNA TRANSIT&TRADING AGENCY USKUDAR--ISTANBUL	Russia	Novorossiisk	04.03.2005	06.04.2005	STABILITY, STRUCTURE AND RELATED EQUIPMENT, ballast, fuel and other tanks, hold 4. bulkhead between cargo hold and ballast tank deep corrosion FIRE SAFETY MEASURES, fire fighting equipment and appliances, fire alarm system isn't ready for use FIRE SAFETY MEASURES, Ventilation, ventilation system of fuel oil tank corroded through FIRE SAFETY MEASURES, Ventilation, ventilation pipe from ballast tankdeep corrosion LIFESAVING APPLIANCES, stowage of lifeboats, lifeboats devits fundation out of requirement
7612838	PRINCE HANI	Comores	1976	3997	general cargo/multi-purpose ship	International Naval Surveys Bureau	MED SEA SHIPPING & TRADING CO, TRIPOLI-LEBANON	Russia	Novorossiisk	05.03.2005	08.03.2005	MOORING ARRANGEMENTS (ILO 147), anchoring devices, port side anchor is missing FIRE SAFETY MEASURES, fire pumps, emergency fire pump is not ready for use
7127431	CALDIRAN	Turkey	1973	1497	general cargo/multi-purpose ship	Turkish Lloyd	PIRILTI DENIZ NAKTIC LTD STI, ISTANBUL-TURKEY	Romania	Constanta	07.03.2005	07.03.2005	FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, aux.engines anti fuel oil spraying system missing

6812845	CAPTAN SALIM	Syrian Arab Republic	1968	1453	general cargo/multi-purpose ship	Turkish Lloyd	YAMAK MARINE TRANSPORT, SYRIA	Romania	Constanta	08.03.2005	10.03.2005	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, certificates for master and officer, engineer officer without c.o.c. SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety equipment (including Exemption), form e in copy ISM RELATED DEFICIENCIES, safety and environmental policy, ism not implemented LOAD LINES, ventilators, air pipes, casings, air vent covers not secured, fwd. pipes without covers LOAD LINES, doors, fwd. watertight doors not tight / corroded
8016134	CHELSEA	Liberia	1981	13597	combination carrier	Lloyd's Register of Shipping	EUROPEAN NAVIGATION INC, ATHENS-GREECE	Romania	Constanta	09.03.2005	10.03.2005	SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety radio (including Exemption), record of radio equipment (form "r") missing
7405091	NAJIB. M	Comores	1976	1875	general cargo/multi-purpose ship	International Naval Surveys Bureau	MIDDLEEAST MARINE WORKS,BELRUT, LIBAN	Romania	Tulcea	09.03.2005	18.03.2005	FIRE SAFETY MEASURES, Emergency Fire Pump, emergency fire pump out of order FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, double jacketed piping system for high pressure fuel diesel to main engine is missing RADIOCOMMUNICATIONS, MF/HF radio installation, mf/hf gmdss installations is out of order

7051931	SEA LION 1	Korea, Democratic People's Republic	1971	1768	general cargo/multi-purpose ship	Korea Classification Society (former Joson Classification Society)	VIBRANI SHIPPING S.A. LIBERIA	Bulgaria	Varna	10.03.2005		<p>FIRE SAFETY MEASURES, Emergency Fire Pump, emergency fire pump out of order. (Korea Classification Society (former Joson Classification Society) )</p> <p>FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, main engine hp fuel pipelines to be in compliance with solas (Korea Classification Society (former Joson Classification Society) )</p> <p>LOAD LINES, ventilators, air pipes, casings, some ventilators air pipes with holes (Korea Classification Society (former Joson Classification Society) )</p> <p>MARPOL - ANNEX I, 15 PPM alarm arrangements, oil bridge water separator with 15 ppm alarm and automatic stopping device not working (Korea Classification Society (former Joson Classification Society) )</p> <p>ALARM SIGNALS, other (alarms), alarm signals for starting co2 fixed systems - out of order. (Korea Classification Society (former Joson Classification Society) )</p> <p>LOAD LINES, machinery space openings, machinery space opening not possible to close. (Korea Classification Society (former Joson Classification Society) )</p> <p>RADIOCOMMUNICATIONS, maintenance/duplication of e</p> <p>RADIOCOMMUNICATIONS, facilities for reception of mar</p> <p>SAFETY OF NAVIGATION, charts, more of ship`s charts</p> <p>CERTIFICATION AND WATCHKEEPING FOR SEAFARE</p> <p>CERTIFICATION AND WATCHKEEPING FOR SEAFARE</p> <p>RADIOCOMMUNICATIONS, reserve source of energy, pd</p> <p>RADIOCOMMUNICATIONS, satellite EPIRB 406MHz/1.6</p>
6602290	WESAM B	Korea, Democratic People's Republic	1965	1197	general cargo/multi-purpose ship	GUARDIAN BUREAU OF SHIPPING	Phoenicia Maritime LLC DE U.S.A.	Russia	Sochi	11.03.2005	18.03.2005	<p>RADIOCOMMUNICATIONS, Performance standards for radio equipment, wrong mmsi number</p> <p>RADIOCOMMUNICATIONS, Performance standards for radio equipment, dsc vhf. malfunction of the keyboard. the button "enter" is inoperative</p>
7610749	LADY HIND	Malta	1977	11866	bulk carrier	Nippon Kaiji Kyokai	H.M.NAVIGATION LTD MALTA	Russia	Novorossiisk	14.03.2005	16.03.2005	<p>FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, main eng.</p> <p>FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, diesel generators</p> <p>FIRE SAFETY MEASURES, Emergency Fire Pump, not start</p> <p>LIFESAVING APPLIANCES, lifeboats, eng. not start</p> <p>PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room</p>

7643746	BILAL CAVUSOGLU	Turkey	1995	886	general cargo/multi-purpose ship	Turkish Lloyd	NALAN CAVUSOGLU	Bulgaria	Bourgas	15.03.2005	16.03.2005	STABILITY, STRUCTURE AND RELATED EQUIPMENT, electric equipment in general, emergency diese generator-out of order (Turkish Lloyd)
7431105	CAPT.AHMED 3	Georgia	1976	1498	general cargo/multi-purpose ship	International Register of Shipping	RED SEA NAVIGATION CO. EGYPT	Romania	Constanta	15.03.2005	20.03.2005	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, certificates for master and officer, 2nd engineer without appropriate certificate CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, certificate for ratings for watchkeeping, two deck ratings without certificates ISM RELATED DEFICIENCIES, safety and enviromental policy, ism not implemented MARPOL - ANNEX I, other (MARPOL/Annex I), deck hydraulic pipes corroded and partly holed FIRE SAFETY MEASURES, fire fighting equipment and appliances, deck fireline pipe corroded and holed ADDITIONAL MEASURES TO ENHANCE MARITIME SAFETY, Continuous synopsis record, missing LIFESAVING APPLIANCES, lifeboats, engine missing FIRE SAFETY MEASURES, fire pumps, emergency firepump without suction
7600079	SOLI	Turkey	1976	10276	bulk carrier	Turkish Lloyd	NAMAR SHIPPING AND TRADING CO. LTD. - TURKEY	Romania	Constanta	15.03.2005		RADIOCOMMUNICATIONS, Operation/maintenance, to gmdss equipment mf - dsc test couldn't be performed by officers in charge
7725972	OULA	Tonga	1978	2341	general cargo/multi-purpose ship	GUARDIAN BUREAU OF SHIPPING ( GBS )	PHOENICIA MARITIME LLC,	Russia	Novorossiisk	15.03.2005	31.03.2005	FIRE SAFETY MEASURES, fire pumps, not ready for used LIFESAVING APPLIANCES, lifeboats, hull cracked

7382718	CAPTAIN DANIEL	Italy	1975	3903	bulk carrier	Registro Italiano Navale	NUOVA MARSERVICE SRL NAPOLI / ITALY	Turkey	Samsun	15.03.2005	15.03.2005	RADIOCOMMUNICATIONS, facilities for reception of marine safety information, navtex messages are unreadable RADIOCOMMUNICATIONS, INMARSAT ship earth station, inmarsat c is out of order by gmdss battery (Registro Italiano Navale) STABILITY, STRUCTURE AND RELATED EQUIPMENT, emergency lighting, batteries and switches, emergency light is not working in s/r (Registro Italiano Navale) FIRE SAFETY MEASURES, personal equipment, fireman outfit are seriously damaged on feet part (Registro Italiano Navale) FIRE SAFETY MEASURES, fire pumps, emergency fire pump is insufficient pressure (Registro Italiano Navale)
8947618	ALEXANDR KARASTOYANOV	Moldova	1964	1866	general cargo/multi-purpose ship	SHIPPING REGISTRY OF REPUBLIC OF MOLDOVA	POSEIDON LTD, KHERSON-UKRAINE	Romania	Constanta	16.03.2005	18.03.2005	SAFETY OF NAVIGATION, Automatic Identification System (AIS), not fitted LIFESAVING APPLIANCES, emergency equipment for 2-way communication, one vhf emergency set out of order MARPOL RELATED OPERATIONAL DEFICIENCIES, oil and oily mixtures from machinery spaces, oily water mixtures into e/r bilge well
5226037	MARMARIS	Turkey	1960	741	general cargo/multi-purpose ship	GOVERNMENT OF REPUBLIC OF TURKEY, MARITIME UNDERSECRETARIAT ( TC )	Paksoy Kardesler Istanbul	Russia	Novorossiisk	16.03.2005		STABILITY, STRUCTURE AND RELATED EQUIPMENT, ballast, fuel and other tanks, leakage of diesel oil from diesel oil tank ( afterpeak ) FIRE SAFETY MEASURES, Ventilation, carriage ( keeping ) of oil in tank without protection (fire) ventilation pipe out of order pumping system CARRIAGE OF CARGO AND DANGEROUS GOODS, holds and tanks, cargo hold have cement boxes
7403005	CASABLANCA S.	Georgia	1976	3368	general cargo/multi-purpose ship	International Register of Shipping	KEREMDE SHIPPING INC	Turkey	Kdz.eregli	16.03.2005	17.03.2005	LIFESAVING APPLIANCES, lifeboats, engine inoperable. (International Register of Shipping) FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, alarm device inoperable (International Register of Shipping)
6602290	WESAM B	Korea, Democratic People's Republic	1965	1197	general cargo/multi-purpose ship	GUARDIAN BUREAU OF SHIPPING	Phoenicia Maritime LLC DE U.S.A.	Russia	Novorossiisk	17.03.2005	18.03.2005	RADIOCOMMUNICATIONS, Performance standards for radio equipment, dcs vhf malfunction of key board. the button "enter" is inoperative

6708563	OMAR	Korea, Democratic People's Republic	1966	495	general cargo/multi-purpose ship	MARITIME BUREAU OF SHIPPING	D&O SHIPPING CO. S.A.	Turkey	Kdz.eregli	17.03.2005	28.03.2005	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, other (STCW), vessel officers do not have flag endorsements or documentary proof of application for endorsements. CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, other (STCW), two deck officer goce licences do not have flag endorsements. RADIOCOMMUNICATIONS, MF radio installation, mf/dsc inoperable. RADIOCOMMUNICATIONS, reserve source of energy, for gmdss equipment inoperable. MARPOL - ANNEX I, oil filtering equipment, improperly with marpol an.1 MARPOL - ANNEX I, pumping, piping and discharge arrangements of oil tankers, unauthorized bypass line installed in the oily water separator(ows) system.it connected from engine bilges to over board.
8121331	NADALINA S	Georgia	1981	2368	general cargo/multi-purpose ship	International Register of Shipping	SEAGATE MARINE Romania	Romania	Constanta	18.03.2005	30.03.2005	ADDITIONAL MEASURES TO ENHANCE MARITIME SAFETY, Continuous synopsis record, missing (International Register of Shipping) SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety radio (including Exemption), with area 1 only next port anaba / algeria (International Register of Shipping) ISM RELATED DEFICIENCIES, safety and environmental policy, i.s.m. not implemented (International Register of Shipping) STABILITY, STRUCTURE AND RELATED EQUIPMENT, stability/strength/loading information and instruments, initial stability calculation missing (International Register of Shipping)
7126073	PRINCESS K	Georgia	1971	3493	general cargo/multi-purpose ship	Germanischer Lloyd	METKAR SHIPPING AND TRADING CO. SRL ROMANIA	Russia	Novorossiisk	23.03.2005	25.03.2005	ALARM SIGNALS, fire alarm, fire alarm station on the bridge. lines 9, 10, 13 are not in working condition LIFESAVING APPLIANCES, lifeboats, engine on life boat ( starboard side ) is not in working condition
7104398	PORDA	Saint Vincent and the Grenadines	1971	2057	general cargo/multi-purpose ship	Hellenic Register of Shipping	ISM GROUP LTD, SYRIA	Turkey	Kdz.eregli	23.03.2005		CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, other (STCW), the master flag state endorsement missing

7507681	ADRIATIC QUEEN	Georgia	1976	5768	general cargo/multi-purpose ship	International Register of Shipping	ALEX SHIPPING & TRADING Co	Russia	Novorossiisk	24.03.2005	11.04.2005	FIRE SAFETY MEASURES, Ventilation, ventilation pipe from bwt 1 damaged FIRE SAFETY MEASURES, Emergency Fire Pump, , low pressure of sea water MARPOL - ANNEX I, 15 PPM alarm arrangements, , electrical boxes and automatic systems out of order CREW AND ACCOMMODATION (ILO 147), Ventilation, heating system of ship's crew accommodation aren't in working condition
7035028	FULL AHEAD	Korea, Democratic People's Republic	1970	1643	general cargo/multi-purpose ship	INTERNATIONAL SHIP REGISTER OF SHIPPING	USTUN DENIZCILIK TURIZM TIC.LTD.- ISTANBUL	Turkey	Kdz.eregli	24.03.2005	25.03.2005	LOAD LINES, freeboard marks, Il certificate shown timber marks.but marking of timber load line marks missing. SHIP'S CERTIFICATES AND DOCUMENTS, prevention of pollution by oil (IOPP), certificate form a recording that ship fitted oil filtering (15ppm) accd. reg.16(5)(a) together. CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, other (STCW), all officers flag endorsement or application for endorsement missing PROPULSION AND AUXILIARY MACHINERY, cleanliness of engine room, and all engine bilges full with oil. FIRE SAFETY MEASURES, jacketed piping system for high pressure fuel lines, leakage tank unit inoperable.
8857992	AGATIS	Georgia	1982	2463	general cargo/multi-purpose ship	Russian Maritime Register of Shipping	DONBASST RANSITSER VICE LTD, MARIUPOL - UKRAINE	Romania	Constanta	25.03.2005	28.03.2005	SAFETY OF NAVIGATION, Automatic Identification System (AIS), out of order (Russian Maritime Register of Shipping)
7906693	IRINA	Georgia	1979	2075	general cargo/multi-purpose ship	International Register of Shipping	SHIPCASE HONOUR S.A. PANAMA	Russia	Novorossiisk	25.03.2005	28.03.2005	FIRE SAFETY MEASURES, Ventilation, ven. of cargo hold deep corr. STABILITY, STRUCTURE AND RELATED EQUIPMENT, other (stability/structure), superstructure FIRE SAFETY MEASURES, fixed fire extinguishing installation, fire alarm station

7000932	RANEEM MOON	Korea, Democratic People's Republic	1969	498	general cargo/multi-purpose ship	INTERNATIONAL MARITIME CLASSIFICATION SOCIETY	RASHA MARITIME CO., TARTOUS	Romania	Constanta	28.03.2005	01.04.2005	LIFESAVING APPLIANCES, rescue boat inventory, engine out of order FIRE SAFETY MEASURES, Ventilation, diesel fuel oil tks quick closing devices are not working properly CERTIFICATION AND WATCHKEEPING FOR SEAFARERS, certificates for master and officer, just one engine officer on board vessel, no evidence regarding automatisaion (ums)
7433323	MED BULKER I	Cambodia	1978	9622	bulk carrier	PHOENIX REGISTER OF SHIPPING	MED BULKER I S.A.,80 BROAD STREET,MONROVIA,LIBERIA	Russia	Tuapse	28.03.2005	28.03.2005	STABILITY, STRUCTURE AND RELATED EQUIPMENT, damage to hull due to weather or ship operation, repair of hole of the outside shell plating in way of cargo hold no.2,port side,not approved by classification society surveyor
7015846	BETUL	Turkey	1970	1245	general cargo/multi-purpose ship	PHOENIX REGISTER OF SHIPPING	BEGUM DENIZCILIK TIC.LTD.STI., ISTANBUL-TURKEY	Romania	Constanta	29.03.2005		FIRE SAFETY MEASURES, other (fire safety), m/e double skin high pressure pipes for fuel system-tank alarm out of order SHIP'S CERTIFICATES AND DOCUMENTS, cargo ship safety equipment (including Exemption), life saving appliances capacity 12 persons, on board crew 13 persons
7739715	BAYRAMOGLU-II	Turkey	1977	766	general cargo/multi-purpose ship	International Naval Surveys Bureau	BAYRAMOGLU DERNIZCILIK TIC STI, DARICA-TURKEY	Romania	Constanta	29.03.2005	29.03.2005	SHIP'S CERTIFICATES AND DOCUMENTS, document of Compliance (DoC/ISM Code), annual verification missing (Turkish Lloyd) RADIOCOMMUNICATIONS, radio log (diary), mf/dsc weekly test not performed/not recorded
8031122	KRAMATORSK	Ukraine	1980	6079	general cargo/multi-purpose ship	Russian Maritime Register of Shipping	COMMERCIAL FLEET OF DONBASS / UKRAINE	Romania	Constanta	29.03.2005		LIFESAVING APPLIANCES, lifeboats, portside lifeboat engine doesn't start
6506135	LINA M	Syrian Arab Republic	1980	1679	general cargo/multi-purpose ship	IRS	Raouf Maritime Co. Tartous - Syria	Ukraine	Odessa	29.03.2005	11.04.2005	0987 Bulkheads - cracking 1210 Overloading

## DISCLAIMER

The information presented hereto can not be used in anyway for commercial purposes; in any sort of products and services which are not freely available to the public without permission of the ROMCOU Committee

the public, without prior consent of the BS MOU Committee.

The accuracy of information contained in the list is the responsibility of the Authority providing the information. Contact information of the BS MOU Member Authorities are given below:

**MEMBER AUTHORITIES :**

BULGARIAN MARITIME ADMINISTRATION  
MINISTRY OF TRANSPORT AND COMMUNICATION  
9, Dyakon Ignatiy Str. 1000 Sofia  
Tel : +359 2 930 09 10 Fax : + 3592 930 09 20

RUSSIAN MARITIME ADMINISTRATION OF MINISTRY OF TRANSPORT  
1, Bldg. 1 , Rozhdestvenka St. Moscow, 103759  
Tel : + 7 095 926 13 80 Fax : + 7 095 926 13 11

MARITIME ADMINISTRATION  
OF THE MINISTRY OF TRANSPORT OF GEORGIA  
4, Shavsheti Street, Batumi, 384517  
Tel : +995 (222) 74925 Fax : + 995 (222) 73929

TURKISH PRIME MINISTRY UNDERSECRETARIAT FOR MARITIME AFFAIRS  
GMK Bulvarı 128, Maltepe / Ankara, 06100  
+ 90 312 3311207 Fax : + 90 312 2313306

Tel :

ROMANIAN NAVAL AUTHORITY  
Constanta Port, RNA Building, 9th floor, Constanta, 900900  
Tel : +40.241/616124 Fax : +40.241/616229

SHIPPING SAFETY INSPECTORATE OF UKRAINE  
Peremogy Ave. 01135, Kiev  
Tel : + 380 44 461 54 44 Fax : + 380 44 461 54 48

14